

M₁₈ BLID

SERVICE PARTS DIAGRAM

Bulletin Date: Mar-20

Starting Serial Number:

VERSION A - E2016

TTI Model Number: 018 139 012, 013, 014, 015, 022, 023

M18 COMPACT BRUSHLESS IMPACT DRIVER

EXAMPLE: IMPORTANT NOTE: Gearcase end cap #24 is LEFT HAND THREAD! 0 Component Parts (Small #) Are Included When Ordering As an aid to assembly, carefully lower the complete front end of the tool (gearcase / impacting system) onto gearcase end cap.
Gently hand tighten front The Assembly (Large #). 60 25 28 29 31 36 43 $52\frac{32}{46}\frac{34}{47}$ 34 end assembly onto gear-case end cap. Be careful not to cross-thread! Once installed by hand, -36 (4x) 29 25 seat gearcase end cap with a good adjustable wrench using light 53 pressure. Do not over tighten! 43 35 LEFT HAND THREAD! 32 46 31 (4x) 48 50 12 13 14 15 16 17 18 $61^{\frac{27}{42}}$ NOTE: The design of Shuttle #35 is similar to other tools that have a spring plate used in conjunction with the shuttle. This tool <u>DOES NOT</u> need a spring plate. 22 15 16 13



- Lightly coat front washer surface of anvil with grease, place a dab in the ball cavities of anvil.
- 35,47 Be sure that oval slot in shuttle is over round pin on switch.
- 48 Coat inside of bushing inside front gearcase with grease.
- 50 **NOTE:** Do not wash impact assembly. Use a clean, dry cloth to wipe away any excess grease or contamination.
- 50 Lightly coat the I.D. of the ring gear and the center of the planet gears of impacting assembly with grease.
- 53 Coat pinion of rotor assembly with grease.
- 62 High voltage wire assembly is a component of the electronics assembly as well as an individual service part.







M18 BLID

SERVICE PARTS LIST

TTI Model Number: 018 139 012, 013, 014, 015, 022, 023

Bulletin Date:
Mar-20

Starting Serial Number:

VERSION A - E2016

M18 COMPACT BRUSHLESS IMPACT DRIVER

ITEM	PART NUMBER	PART DESCRIPTION	QTY (PCS)
1	690258004	RETAINING RING	1
2	690266002	WASHER	1
3	690261003	SPRING	1
4	690260056	SLEEVE	1
8	523732001	PLASTIC WASHER	1
9	670220001	4.0MM STEEL BALL	1
10	621352139	1/4" HEX ANVIL	1
11	670219001	5MM STEEL BALL	1
12	693116042	HAMMER	1
13	670221001	3.0MM STEEL BALL	29
14	680335092	WASHER	1
15	693164033	SPRING	1
16	611575021	PLANET GEAR	2
17	680015001	3/16" STEEL BALL	2
18	621338037	CAM SHAFT	1
19	671565003	PLANET GEAR PIN	2
20	690426002	WASHER	1
21	681949004	BALL BEARING	1
22	611574012	RING GEAR	1
23	681758004	BALL BEARING	1
24	642049002	GEARCASE END CAP	1
25	660274003	4-20 X .625 SCREW	8
27	661082002	6-32 X 5/16" SCREW	1
28	-	HOUSING COVER - RIGHT	1
29	660837003	M3.0 X 22.5MM SCREW	1
31	560075002	RUBBER SLUG	4
32	280160190	PCBA	1
34	298062009	STATOR ASSEMBLY	1
35	528061001	FORWARD/REVERSE SHUTTLE	1
36	562951001	RUBBER SLUG	4
42	634138001	BELT CLIP	1
43	-	HOUSING SUPPORT - LEFT	1
44	691093001	COMPRESSION SPRING	1
46	302119005	TERMINAL CONNECTOR BLOCK	1
47	760521006	ON-OFF SWITCH	1
48	203390001	GEARCASE ASSEMBLY WITH BUSHING	1



M₁₈ BLID

SERVICE PARTS LIST

TTI Model Number: 018 139 012, 013, 014, 015, 022, 023

Bulletin Date:
Mar-20

Starting Serial Number:

VERSION A - E2016

M18 COMPACT	BDI IEUI EEG	IMPACT	DDIVED
WITO CUMPACT	DRUJHLEJS	HIVIPACI	DRIVER

ITEM	PART NUMBER	PART DESCRIPTION	QTY (PCS)
50	203392001	IMPACTING ASSEMBLY	1
52	203395003	ELECTRONICS ASSEMBLY	1
53	203394001	ROTOR ASSEMBLY	1
60	203427001	HOUSING ASSEMBLY	1
61	202132001	BELT CLIP KIT	1
63	941046489	SERVICE NAMEPLATE	1
64	307640021	DYNACASE ASSEMBLY 018139012, 013 VERSION	1
64	302862024	BMC 018139014, 015, 022, 023 VERSION	1
1200	-	TYPE J GREASE	1



M18 BLID

SERVICE INSTRUCTION


TTI Model Number: 018 139 012. 013. 014. 015. 022. 023

M18 COMPACT BRUSHLESS IMPACT DRIVER

Bulletin Date: Mar-20

Starting Serial Number:

VERSION A - E2016



SUPPORT, BE SURE THAT THERE ARE NO INTERFERENCES.